

Vehicle Inspection Report



Applus⁺
Technologies, Inc.

9855645

9855645



Quality Management System Certified Company

www.ecy.wa.gov/programs/air/airhome.html

www.emissiontestwa.com

Inspection Summary	Payment Amount*: \$15.00	Payment Type: CHECK
Test Result: PASS	*This is your receipt. Test valid for 365 days.	Test Counter: 1
	Test ID Number: 1411302188772	Software Version: 2.2

Vehicle Information		PLEASE VERIFY VIN AND LICENSE NUMBER ARE CORRECT	
VIN: XXXXXXXXXX	License Number: VTM 29	License State: OR	
Fuel Type: GAS	Vehicle Type: CAR	Body Type: SEDAN	Model Year: 1996
Make: VOLVO	Model: 850	Engine Size: 2.4 L	GVWR: <=9,500
Cylinders: 5	Transmission: AUTOMATIC	Exhaust: SINGLE	AES ID #: N/A
	Lookup Table ID: 15157	Equiv Test Wt: 3500	Horsepower: 57

Inspection Station Information	Station: 14	Lane: 1
Start Date/Time: 04/07/2011 03:06 PM	Operator 1: VIKTORS VIKTOR	Operator 2: CRAIG CRAIG

Gas Cap Test Results	Cap 1: PASS	Cap 2: N/A
Result: PASS	Cap 3: N/A	Cap 4: N/A

This emission test was performed in accordance with federal regulations on emission tests (40CFR 85 Subpart W) by Applus Technologies, Inc. for the Department of Ecology.

Test Results		Test Type: ASM			
Overall ASM Result: PASS			Number of Restarts: 0		
	HC (PPM)	CO (%)	CO+CO2 (%)	O2 (%)	RPM
Cruise Limit:	150	1	6	N/A	N/A
Cruise Emissions:	24	0.03	15.43	0.04	N/A
Cruise Result:	PASS	PASS	N/A	N/A	N/A
Idle Limit:	220	1.2	6	N/A	N/A
Idle Emissions:	9	0	15.4	0.01	860
Idle Result:	PASS	PASS	N/A	N/A	N/A

Repair Information	Emission Specialist #:	Date/Time:
By signing this form, I am acknowledging that I diagnosed/attempted repairs to this vehicle, after the initial test failure, in an effort to reduce failing emission reading(s). I am currently an Ecology Authorized Emission Specialist.		
Printed Name:	Signature:	

MAKING FALSE STATEMENTS TO OBTAIN A CERTIFICATE OF COMPLIANCE/ACCEPTANCE IS A VIOLATION OF WAC 173-422-190

IMPORTANT INFORMATION ON REVERSE SIDE